

# Industrial Repair Services of Louisiana <sup>1</sup>

A Manuel & Tedder Enterprise  
17188 Airline Highway, Suite M-144  
Prairieville, Louisiana 70769

Parts just received for the Honeywell TDC3000 Distributed Control Systems  
Please call or email to check for current pricing and availability.

Two Year Warranty on all Items

| Part Number        | Description                                | QTY |
|--------------------|--|-----|
| 3067031-001        | MDB-DG/Interface Adapter 450004 rev A1     | 1   |
| 3070783-3          | Diskette Bootstrap                         | 2   |
| 30731808-001       | Regulator Card                             | 2   |
| 30731808-003       | Regulator Card                             | 1   |
| 30731811-3         | Output Card                                | 2   |
| 30731814-4         | PWAY Hwy 2                                 | 1   |
| 30731817-4         | PWAY Hwy 1                                 | 1   |
| 30731820-001       | PWA DEP Interface                          | 7   |
| 30731823-001       | A/D MUX                                    | 3   |
| 30731832-001       | Driver/Receiver Processor Board            | 2   |
| 30732037-001       | Panel Display Module                       | 1   |
| 30732219-001       | PWB, Cable Logic                           | 1   |
| 30732233-001       | PWB, Cable Driver & Detectors              | 2   |
| 30732254-001       | Display Generator DMA                      | 1   |
| 3073233-001        | GPCI Driver Receiver                       | 1   |
| 30732438-001       | Display Generator Card MNY MW-1 940        | 1   |
| 30733155-001       | Switching Regulator                        | 1   |
| 30734558-001       | Battery Backup                             | 1   |
| 30735857-1         | CMOS Memory                                | 4   |
| 3073594-2          | PWB Trend Memory                           | 1   |
| 30750218-010       | 12KROM/!K RAM Assembly                     | 1   |
| 30750218-8         | 12KROM/!K RAM Assembly                     | 1   |
| 30750338-003       | PWA Highway #2                             | 1   |
| 30750990-001       | PWB Keyboard Interface                     | 1   |
| 30751853 Rev HW-10 | PWA EDAC(10) Card Error Direct and Correct | 2   |
| 30751856-1         | PWA, Op Std Memory 128K                    | 6   |
| 30758988-001       | Keyboard Interface                         | 1   |
| 42622268-002       | 16 Channel AI (Hart) FTA                   | 1   |
| 51107403-100 P, V  | LCN I/O Card                               | 6   |
| 51107954-100B      | I/O MCPUC                                  | 1   |
| 51108607-906 K     | Card Cage                                  | 1   |
| 51109336-100 A     | I/O FDD                                    | 1   |
| 51109684-100       | PM/APM 20 Amp Power Supply                 | 2   |

Industrial Repair Services of Louisiana  
A Manuel & Tedder Enterprise  
17188 Airline Hwy, Suite M-144  
Prairieville, Louisiana 70769

Phone: 800-791-1756  
Fax: 225-673-6419  
Email: [sales@irsla.com](mailto:sales@irsla.com)  
Web Site: [www.irsla.com](http://www.irsla.com)

# Industrial Repair Services of Louisiana <sup>2</sup>

A Manuel & Tedder Enterprise  
17188 Airline Highway, Suite M-144  
Prairieville, Louisiana 70769

|                              |  |    |
|------------------------------|--|----|
| 51109818-100                 | Power Supply   | 1  |
| 5112009 FW Rev C             | 4DP7APXPM Prom/RAM for HLPIU                           | 1  |
| 51190916-102                 | Communication Hub with terminators                     | 1  |
| 51195066-100                 | 5-Slot Chassis Power Supply                            | 0  |
| 51195096-200                 | PLCI I/O Card  | 2  |
| 51195479-100 Rev B           | Cables   | 4  |
| 51196655-100                 | Power Supply Dual Node CE                              | 5  |
| 51196742-500                 | Video Cable TTL 36 01                                  | 1  |
| 51196989-100 Rev R           | Universal Regulator for all highway boxes except LLPIU | 1  |
| 51197004-300                 | Power Supply   | 1  |
| 51197564-200                 | UCN Extender   | 2  |
| 51198947-100                 | PM Power Supply  | 43 |
| 51201557-100                 | Fiber Optic Coupler Module                             | 4  |
| 51201557-150                 | Fiber Optic  | 10 |
| 51201557-350                 | Fiber Optic  | 11 |
| 51204166-175                 | Digital Output Relay Termination Assy                  | 7  |
| 51204170-150                 | STI Enhanced Power Termination Assy                    | 2  |
| 51204170-250                 | Power Termination                                      | 5  |
| 51204172-150                 | Analog Output Term.                                    | 2  |
| 51204172-175                 | Analog Output 16 Termination Assy                      | 1  |
| 51204175-175                 | Analog Output Term.                                    | 1  |
| 51301074-100                 | 1 PWA, MUX RTD LOGIC                                   | 1  |
| 51301470-100 Rev B           | 4DP7APXDH122   | 1  |
| 51302780 Rev A               | PXAD21-A 4DP7A   | 1  |
| 51302793-100 Rev B           | PX1021 4DP7A HLPIU I/O Bus Controller                  | 1  |
| 51302864 Rev C               | IPXOD41D BD  | 2  |
| 51302951-100 rev D           | Compeo/Honeywell 4DP7APX1Z/4DP7APX1322F                | 4  |
| 513034033-045 B              | Cable  | 1  |
| 51303654-092 F               | Power Trend Cable (use w/51109818)                     | 1  |
| 51303932-476                 | Serial Interface FTA - Modbus                          | 1  |
| 51303948-100                 | 48V Battery Backup Module (Rack Only)                  | 7  |
| 51303948-100                 | Power Supply Assembly                                  | 2  |
| 51303978-400                 | HPM I/O Link Interface Card                            | 1  |
| 51303979-400                 | HPM I/O Link Interface Card                            | 7  |
| 51304037183 B                | Cable  | 1  |
| 51304040-101 A               | Ribbon Cable FDD                                       | 1  |
| 51304042-100 (with 51303976- | HPM Communication Card                                 | 7  |

Industrial Repair Services of Louisiana  
A Manuel & Tedder Enterprise  
17188 Airline Hwy, Suite M-144  
Prairieville, Louisiana 70769

Phone: 800-791-1756  
Fax: 225-673-6419  
Email: [sales@irsla.com](mailto:sales@irsla.com)  
Web Site: [www.irsla.com](http://www.irsla.com)

# Industrial Repair Services of Louisiana <sup>3</sup>

A Manuel & Tedder Enterprise  
 17188 Airline Highway, Suite M-144  
 Prairieville, Louisiana 70769

|                             |  |     |
|-----------------------------|--|-----|
| 400)                        |  |     |
| 51304084-175                | Pulse Input FTA                              | 1   |
| 51304270-100 D              | EPDG I/O                                     | 1   |
| 51304337-150                | High Level Analog Input/STI FTA              | 15  |
| 51304362-100                | Low Level Analog Input Multiplexer Processor | 1   |
| 51304362-150                | Low Level Analog Input Multiplexer Processor | 11  |
| 51304362-300                | Serial Interface I/O Processor               | 1   |
| 51304362-350                | Serial Interface I/O Processor               | 4   |
| 51304386-150                | Pulse Input IOP                              | 3   |
| 51304392-100 B              | Power Cable FDD                              | 1   |
| 51304399-100 B              | Cable  | 1   |
| 51304419-150                | I/O Link Extender                            | 32  |
| 51304421-100                | PLCG Relay Panel                             | 4   |
| 51304437-150                | Analog Input Low Level w/ 4ea. 51304085-100  | 2   |
| 51304439-175                | Digital Input FTA 120Vac                     | 2   |
| 51304441-175                | Digital Input 24 VDC 32 Point                | 14  |
| 51304471-150                | Low Level Analog Input                       | 1   |
| 51304481-150                | Low Level Analog Input Processor             | 2   |
| 51304485-150                | Digital Input Processor IOP                  | 12  |
| 51304487-100                | Digital Output Processor                     | 1   |
| 51304487-150                | Digital Output Processor 16 Point            | 10  |
| 51304493-100 Rev F,G, K     | HPM Modem Card                               | 2   |
| 51304501-100 Rev B          | HPM Redundancy Driver                        | 8   |
| 51304511-200                | NIM Modem                                    | 12  |
| 51304516-250                | Smart Transmitter Interface Processor        | 72  |
| 51304525-100 w/51303982-400 | HPM Control Card                             | 8   |
| 51304540-200                | LCNE2 Paddle board                           | 7   |
| 51304589-150                | Assembly                                     | 8   |
| 51304648-175                | Digital Output FTA 120/240 Vac               | 1   |
| 51304650-150                | Digital Output FTA 3-30Vdc Solid State       | 2   |
| 51304754-150                | High Level Analog Input 16 Point             | 132 |
| 51304907-200                | SPCII Paddle Board                           | 1   |
| 51305072-100                | CLCN A/B I/O Board CE                        | 1   |
| 51305072-200                | CLCN A I/O Board CE                          | 9   |
| 51305072-300                | CLCN B I/O Board                             | 7   |
| 51305701-100                | UDH12  | 1   |
| 51305776-100 Rev D          | OEP/IKB Module Assembly                      | 1   |
| 51306148-152                | Digital Output Term.                         | 1   |

Industrial Repair Services of Louisiana  
 A Manuel & Tedder Enterprise  
 17188 Airline Hwy, Suite M-144  
 Prairieville, Louisiana 70769

Phone: 800-791-1756  
 Fax: 225-673-6419  
 Email: [sales@irsla.com](mailto:sales@irsla.com)  
 Web Site: [www.irsla.com](http://www.irsla.com)

# Industrial Repair Services of Louisiana <sup>4</sup>

A Manuel & Tedder Enterprise  
17188 Airline Highway, Suite M-144  
Prairieville, Louisiana 70769

|                              |   |    |
|------------------------------|---|----|
| 51309104-175                 | Lmux/SPI Power Adapter                  | 1  |
| 51309148-125                 | Digital Output 120VAC Relay             | 1  |
| 51309148-175                 | Digital Output 120 VAC Relay Assy       | 6  |
| 51309204-125                 | LLMux, SI, SDI Power Adapter FTA        | 1  |
| 51309204-175                 | LLMux, SI, SDI Power Adapter FTA        | 13 |
| 51309212-125                 | LLMUX Digital Outuput                   | 2  |
| 51309212-175                 | LLMUX Digital Outuput                   | 5  |
| 51309213-125                 | Low Level Multiplexer Thermocouple FTA  | 16 |
| 51309213-175                 | FTA, LLMUX TC w/ 51309210-175           | 1  |
| 51309276-150                 | HPM I/O Link CC                         | 2  |
| 51400646-100 Rev F           | Fan Assembly                            | 1  |
| 51400659-100 Rev E           | MEM Memory Circuit Board                | 1  |
| 51400664-100 Rev G           | MCPU Processor Circuit Board            | 1  |
| 51400666-100 Rev H           | PIC Vide Circuit Board                  | 1  |
| 51400667-100 Rev F           | LCN Circuit Board                       | 2  |
| 51400668-100 Rev L           | WDC Controller Circuit Board            | 2  |
| 51400669-100 Rev J           | FDC Floppy Disk Circuit Board           | 3  |
| 51400715-200 Rev K, M        | 10 Slot Logic Power Supply              | 2  |
| 51400901-100 Rev F           | EMPU Circuit Board                      | 1  |
| 51400910-100 Rev E           | EMEM Memory Circuit Board               | 3  |
| 51400992-100 Rev C           | PDG Circuit Board                       | 1  |
| 51400997-100 Rev D           | PLCI Circuit Board                      | 1  |
| 51401052-100                 | Smart Peripheral Controller card        | 1  |
| 51401072-300 Rev A           | QEM-3 Memory Circuit Board              | 1  |
| 51401286-100                 | EPDG                                    | 1  |
| 51401288-100 Rev L, N        | HPK2-2 Processor Circuit Board          | 2  |
| 51401288-200                 | HPK2-3 Processsor Circuit Board         | 1  |
| 51401291-100                 | LLCN                                    | 1  |
| 51401496-100                 | Fan Asembly                             | 5  |
| 51401532-150                 | Back Panel                              | 6  |
| 51401547-100 Rev A           | PM IO Card File                         | 1  |
| 51401547-100 Rev B           | PM IO Card File                         | 6  |
| 51401583-100                 | EPNI - NIM                              | 5  |
| 51401598-200 w/ 51304685-200 | HPM Advanced Commun                     | 1  |
| 51401632-150                 | HPM 15 Slot Back Panel                  | 45 |
| 51401635-150                 | HPM Communication and Control Processor | 17 |
| 51401642-150                 | I/O MODULE HIGH PERFORMANCE LINK        | 19 |
| 51401946-100                 | Cards                                   | 1  |

Industrial Repair Services of Louisiana  
A Manuel & Tedder Enterprise  
17188 Airline Hwy, Suite M-144  
Prairieville, Louisiana 70769

Phone: 800-791-1756  
Fax: 225-673-6419  
Email: [sales@irsla.com](mailto:sales@irsla.com)  
Web Site: [www.irsla.com](http://www.irsla.com)

# Industrial Repair Services of Louisiana <sup>5</sup>

A Manuel & Tedder Enterprise  
17188 Airline Highway, Suite M-144  
Prairieville, Louisiana 70769

|              |   |    |
|--------------|---|----|
| 51402089-100 | EPDG2 for Universal Station             | 1  |
| 51402447-200 | EPDGC I/O for Universal Station         | 1  |
| 51402455-100 | Dual Node card file w/Fan assembly      | 10 |
| 51402525-125 | Digital Input SOE                       | 14 |
| 51402573-150 | HPM UCN Interface                       | 22 |
| 51402599-150 | D Back Plane                            | 8  |
| 51402619-120 | A/C Res.                                | 2  |
| 51402625-125 | Digital Input Processor SOE             | 75 |
| 51402625-175 | Digital Input Processor SOE             | 5  |
| 51402755-100 | K4LCN                                   | 5  |
| 51403282-200 | LNCP4 W/ Cable for GUS station          | 1  |
| 51403422-150 | HPM Communication and Control Processor | 2  |
| 51404172-175 | Power Back Panel                        | 21 |
| 5439-929     |   | 2  |
| 80363969-150 | Analog Output Processor 16 Channel      | 77 |
| 80363975-150 | Digital Output Processor 32 Channel     | 46 |
| 80366189-175 | Digital Output FTA                      | 5  |
| 80366195-150 | High Level Analog Input/STI FTA         | 13 |
| 80366481-125 | Analog Output Term.                     | 1  |
| 80366481-175 | Analog Output Processor 16 Channel      | 6  |

Industrial Repair Services of Louisiana does not sell or provide software licensing for any items sold. All software is property of the original manufacture and must be purchased from them directly. All firmware and proprietary information is sole property of the OEM and we do not provide or sell any such items.

For the most recent copy of this inventory please visit our web site by clicking below.

[Updated Honeywell TDC3000 Inventory](#)

Industrial Repair Services of Louisiana  
A Manuel & Tedder Enterprise  
17188 Airline Hwy, Suite M-144  
Prairieville, Louisiana 70769

Phone: 800-791-1756  
Fax: 225-673-6419  
Email: [sales@irsla.com](mailto:sales@irsla.com)  
Web Site: [www.irsla.com](http://www.irsla.com)